



E-2225264

SAMPLE NOT COLLECTED BY UNIT STAFF

WATER QUALITY MONITORING UNIT
AMRIT BHAWAN, VINAY MARG, CHANAKYAPURI
QUALITY CONTROL & TECHNICAL AUDIT CELL
NEW DELHI MUNICIPAL COUNCIL
ISO 9001-2015 CERTIFIED

1. Name & Address of Sender: - Principal, St. Columba's School, Ashoka Place, New Delhi-110001.
2. Date of Receiving/Collection: - 26/02/2026
3. Sample No.:- 1909-1912
4. Sealed Sample (Yes/No):- Yes

Drinking Water Testing Report
Test - Results

Sr. No	Location, Date & Time of Sample Collection Site	Colour (Pt-Co Scale)	Taste & Odour	Turbidity (NTU)	p ^H	Total Hardness (as CaCO ₃) (mg/l)	TDS (mg/l)	Iron (as Fe) (mg/l)	Chloride (as Cl) (mg/l)	Residual Free Chlorine (mg/l)	Coliform Org. MPN / (100 ml)	E Coli. MPN / (100 ml)
1.	Senior School	5	Agreeable	0.4	7.7	120	203	<0.02	50	0.2	NIL	—
2.	Middle school ground	5	Agreeable	0.7	7.7	126	212	<0.02	52	0.2	NIL	—
3.	Middle School	5	Agreeable	0.3	7.8	144	242	<0.02	60	NIL	NIL	—
4.	Junior School.	5	Agreeable	0.4	7.6	120	202	<0.02	50	0.4	NIL	—
5.												
BIS : 10500 2012	Acceptable Limits	05 max.	Agreeable	1 max.	6.5 To 8.5	200 max.	500 max.	0.3 max.	250 max.	0.2 min.	NIL	NIL
	Permissible Limits (in the absence of alternate source.)	15	Agreeable	5	No relaxation	600	2000	No relaxation	1000	1	NIL	NIL

Remarks:- With respect to above tests, all the above water samples except Sr. No. can/ cannot be considered fit for drinking purposes. However minimum residual free chlorine 0.2 mg/l should be done to avoid contamination.

2/3/26

02-03-26

Chemist/Lab Technician

Lab. Technician/Asstt.

- Note:-
- 1) water samples will be destroyed after testing unless otherwise specified by party.
 - 2) If the sample is not collected by our WQMU staff, the sender/ party will be responsible for any wrong, incomplete or misleading information given by him.
 - 3) This test report is not valid for any legal proceeding.