



BY UNIT STAFF
SAMPLE NOT COLLECTED

WATER QUALITY MONITORING UNIT
AMRIT BHAWAN, VINAY MARG, CHANAKYAPURI
QUALITY CONTROL & TECHNICAL AUDIT CELL
NEW DELHI MUNICIPAL COUNCIL
ISO 9001-2015 CERTIFIED

1. Name & Address of Sender:- *principal, St. Columbas School, Ashok*
2. Date of Receiving/Collection:- *29-3-2023.* *place, New Delhi.*
3. Sample No.:- *3341-3345*
4. Sealed Sample (Yes/No):-

DRINKING WATER TESTING REPORT
TEST-RESULTS

Sr. No.	Location, Date & Time of Sample Collection Site	Colour (Pt-Co Scale)	Taste & Odour	Turbidity (NTU)	pH	Total Hardness (as CaCO ₃) (Mg/L)	TDS (Mg/L)	Iron (as Fe) (Mg/L)	Chloride (as Cl) (Mg/L)	Residual free Chlorine (Mg/L)	Coliform org. MPN / (100 ML)	E.Coli MPN/ 100 ML
1. 'A'	Senior School	5	<i>Agreeable</i>	0.3	7.8	176	324	0.21	90	NIL	NIL	—
2. 'B'	Middle School, play area.	5	-do-	0.4	7.8	178	324	0.22	92	NIL	NIL	—
3. 'C'	Middle School	5	-do-	0.3	7.8	146	279	0.16	74	NIL	NIL	—
4. 'D'	Junior School	5	-do-	0.4	7.8	144	273	0.14	72	NIL	NIL	—
5. 'E'	Middle School, Outer area.	5	-do-	0.3	7.7	150	282	0.18	76	NIL	NIL	—
BIS: 10500 2012	Acceptable Limits	05 max	Agreeable	1 max.	6.5 To 8.5	200 max.	500 max.	0.3 max.	250 max.	0.2 min.	NIL	NIL
	Permissible Limits (in the absence of alternate source.)	15	Agreeable	5	No relaxation	600	2000	No relaxation	1000	1	NIL	NIL

Remarks:- With respect to above tests, all the above water samples ~~except~~ Sr. No. *-----* ~~can/cannot~~ be considered fit for drinking purposes. However minimum residual free chlorine 0.2 Mg/L should be done to avoid contamination.

3341/23
Chemist/Lab. Technician

03/04/23
Lab. Technician/Asstt.

- Note:-**
- 1) water samples will be destroyed after testing unless otherwise specified by party.
 - 2) If the sample is not collected by our WQMU staff, the sender/party will be responsible for any wrong, incomplete or misleading information given by him.
 - 3) This test report is not valid for any legal proceeding.